
























A	784x430	2/3
B	784x430	2/3
C	704x430	2/3
D	704x430	2/3
E	1800x430	1/3
F	1768x430	1/3
G	2x1800x 80	1/3
H	2x 638x 80	1/3

I	2x 633x542	3/3
J	2x 603x410	2/3
K	2x 365x1795	1/3
L	6x 400x140	2/3
M	6x 473x140	3/3
N	3x 208x542	3/3
O	3x 502x395	1/3
P	2x 430x 64	1/3

44x 10174	50x 10013	44x 50317	4x 40013	3x L= 400 mm 50955	8x 50249	8x 50332	2x 50273
5x 20188	2x 51066	2x 10060	51x Φ 3,5/16 10001	29x Φ 3,5/20 10002	6x Φ 3,5/30 10004	2x Φ 6/80 10021	 10033





If you face difficulties in connecting surface F with parts C & D , please turn the F surface sideways.

