
















069-000064

Assembly Drawing






Parts list

TOOLS





No:	SZ (W*D*H)	QTY
①	2000*900*25	1
②	715*880*25	1
③	2165*720*16	1
④	250*60*16	2
⑤	500*60*16	2
⑥	1800*400*25	1
⑦	1780*635*16	1
⑧	635*552*16	1
⑨	364*550*16	1
⑩	364*60*16	1
⑪	635*360*16	2
⑫	514*360*16	1
⑬	546*190*16	3
⑭	350*120*16	6
⑮	456*105*16	3
⑯	467*395*4	3
⑰	514*60*16	1




Step:1





Step:2






Step:3






Step:4







Step:5









Step:6






Step:7



Step:8



Step:9



Finish

