

















069-000066

Assembly Drawing






Parts list

TOOLS





No:	SZ (W*D*H)	QTY
①	1400*750*25	1
②	800*300*16	1
③	450*60*25	1
④	1400*400*16	1
⑤	1400*400*16	1
⑥	603*398*16	1
⑦	603*380*16	1
⑧	1328*603*16	1
⑨	603*130*16	1
⑩	603*362*16	2
⑪	340*360*16	1
⑫	599*470*16	1
⑬	409*198*16	3
⑭	350*120*16	6
⑮	319*105*16	3
⑯	330*355*4	3
⑰	603*100*16	1






Step:1






Step:2









Step:3




Step:4




Step:5




Step:6






Step:7



Step:8



Step:9



Finish

