

















069-000068

Assembly Drawing






Parts list

TOOLS





No:	SZ (W*D*H)	QTY
①	1800*900*25	1
②	1200*300*16	1
③	600*60*25	1
④	1600*400*16	1
⑤	1600*400*16	1
⑥	603*398*16	1
⑦	603*380*16	1
⑧	1528*603*16	1
⑨	603*130*16	1
⑩	603*362*16	2
⑪	390*360*16	1
⑫	599*520*16	1
⑬	509*198*16	3
⑭	350*120*16	6
⑮	419*105*16	3
⑯	430*355*4	3
⑰	603*100*16	1






Step:1






Step:2









Step:3




Step:4




Step:5




Step:6



Step:7



Step:8





Step:9

N




X30




Finish

H



X2

M



X20 4*20

