



069-000070

Assembly Drawing




Parts list

TOOLS




A

X32




B

X20




C

X4




D

X2




E

X24 3.5*14




F

X12



G

X10





H

X20






No:	Specification(W*D*H)	QTY
①	800*400*25	1
②	1970*380*16	2
③	1970*764*16	1
④	764*362*16	2
⑤	764*60*16	1
⑥	763*355*16	3
⑦	734*396*16	2

Step:1




Step:2



Step:3


A


X6



B

X4







Step:4





F

X12





Step:5



Finish

