



069-000103


Assembly Drawing





Parts list


TOOLS





A
X28


D
X72 3.5*14

G
X5

B
X6



E
X2

C
X8



F
X2

No:	Specification (W*D*H)	QTY
①	1000*1192*16	2
②	392*1192*16	1
③	730*170*16	2
④	730*768*16	2
⑤	136*200*16	4


Step:1




Step:2






Step:3






Step:4



Step:5



Step:6



Finish

