



069-000112
Assembly Drawing

TOOLS




 X79	 X42	 X24	 X1
 X2	 X1	 X2	 X1
 X29 3.5*14	 X4 3.5*40	 X16 3.5*20	 X2
 X6 6*25	 X6 4*25	 X2	 X6




X12



X12



Step:1


X12


X4




Step:2


X32


X20



X6


X12 3.5*20



Step:3



X6 6*25



Step:4


X8


X4




Step:5


X4


X2



X2



Step:6

No:	Specification(W*D*H)	QTY	No:	Specification(W*D*H)	QTY
①	1400*800*50	1	⑪	600*590*15	1
②	690*790*50	1	⑫	558*418*15	4
③	1245*80*15	1	⑬	200*417*15	2
④	150*80*15	1	⑭	300*417*15	1
⑤	570*80*15	1	⑮	396*402*15	1
⑥	1095*400*15	1	⑯	396*150*15	1
⑦	1600*450*15	2	⑰	390*100*15	2
⑧	1598*558*15	1	⑱	312*85*15	1
⑨	558*80*15	1	⑲	323*395*4	1
⑩	558*418*15	1			


X9



Step:7


X2



X1


X1


X4 3.5*20


X16 3.5*14



X4 3.5*40



Step:8


X12 3.5*14


X2



Step:9

