


069-000116
Assembly Drawing

TOOLS



A
X24




B
X12



C
X3



D
X1



E
X4




F
X12 3.5*40




G
X71 3.5*14





H
X12





No:	Specification(W*D*H)	QTY
①	400*440*25	1
②	550*420*15	2
③	550*360*15	1
④	360*401*25	1
⑤	396*140*15	2
⑥	396*262*15	1
⑦	390*80*15	4
⑧	390*160*15	2
⑨	304*65*15	2
⑩	304*145*15	1
⑪	315*395*4	3




STEP:1

A
X12



B
X12





STEP:2

A
X8




C
X2




G
X30 3.5*14



F
X8 3.5*40





STEP:3

A
X4



C
X1




G
X15 3.5*14




F
X4 3.5*40





STEP:4





STEP:5

E
X4



G
X16 3.5*14





STEP:6