



069-000118
Assembly Drawing

TOOLS



A X79	B X42	C X24	D X1
E X2	F X1	G X2	H X1
I X29 3.5*14	J X4 3.5*40	K X16 3.5*20	L X2
M X6 6*25	N X6 4*25	O X2	P X6




A

X12

B

X12




Step:1

A

X12

B

X4



Step:2

A

X32

B


X20

P

X6

K


X12 3.5*20



Step:3

M

X6 6*25




Step:4

A

X8

B

X4



Step:5

A


X4

B

X2

O


X2



Step:6

A

X9



Step:7

A

X2

F

X1

H

X1

K


X4 3.5*20

I

X16 3.5*14

J

X4 3.5*40




Step:8

I

X12 3.5*14

G

X2



Step:9

No:	Specification(W*D*H)	QTY	No:	Specification(W*D*H)	QTY
①	1600*800*50	1	⑪	600*590*15	1
②	690*790*50	1	⑫	558*418*15	4
③	1445*80*15	1	⑬	200*417*15	2
④	150*80*15	1	⑭	300*417*15	1
⑤	570*80*15	1	⑮	396*402*15	1
⑥	1295*400*15	1	⑯	396*150*15	1
⑦	1600*450*15	2	⑰	390*100*15	2
⑧	1598*558*15	1	⑱	312*85*15	1
⑨	558*80*15	1	⑲	323*395*4	1
⑩	558*418*15	1			

