








## PART LIST








## HARDWARE LIST







STEP 1



- |   |    |
|---|----|
| A   | X2 |
| <br>DIA6x30mm  |    |
| B   | X2 |
| <br>DIA12mm    |    |
| C   | X2 |
| <br>DIA10x12mm |    |
| D   | X1 |
|                |    |
| E   | X4 |
|                |    |

STEP 2



- |  |    |
|--|----|
| A  | X4 |
| <br>DIA6x30mm |    |
| B  | X4 |
| <br>DIA12mm   |    |
| D  | X1 |
|               |    |