











ASSEMBLY DRAWING

1STEP



2STEP



							
Ax2	Bx4	Cx1	Dx16	Ex16	Fx1	Gx6	Hx4