










230-000114


1  X1	2  X1	3  X1	4  X1	5  X1	6  X1	7  X1
8  X2	9  X1	10  X2	11  X1	12  X2	13  X1	14  X1
15  X1	16  X1	17  X1	18  X1	19  X1	20  X2	21  X2
22  X2	23  X2	24  X2	25  X1	A  X56	B  X56	C 6.3X50)  X15
D (3.5X12)  X29	E  X4	F (5X50)  X8	G  X2	H  X1	I  X1	

Step 1




D x8

Step 2




C x3

Step 3




A	x16
B	x16

Step 4




Step 5




A	x8
B	x8
C	x4

Step 6




C	x4
---	----

Step 7




Step 8




A	x4
B	x4

Step 9




A	x14
B	x14

Step 10




A	x4
C	x4
B	x4

Step 11




A	x6
B	x6

Step 12





A	x2
B	x2
F	x4



D	x4
---	----

Step 13



D	x12
---	-----

Complete

