









|                                                                                                        |                                                                                                   |                                                                                                        |                                                                                                    |                                                                                               |
|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| 1.x1<br>            | 2.x1<br>       | 3.x2<br>            | 4.x2<br>      | 5.x4<br> |
| 6.x1<br>            |                                                                                                   |                                                                                                        |                                                                                                    |                                                                                               |
| A.x8<br>M8x50mm<br> | B.x4<br>M8<br> | C.x6<br>M6x35mm<br> | D.x4<br>M6<br> | E.x1<br> |
| F.x1<br>            | G.x8<br>       | H.x4<br>M8x35mm<br> | I.x4<br>       |                                                                                               |

