


292-000104

Assembly Instruction



A



X01

D



X02

B




X04

E



X01

C



X04

F



X01

G



6*40MM

X04

H



6*35MM

X04

I



X08

J



6*16MM

X04

K



6*16*1.5MM


X04

L




X08


STEP 1




STEP 2




STEP 3




STEP 4



STEP 5



STEP 6



STEP 7

