



1

Step 1 : 50% tighten
screw at this stage.




2

Step 2 : 50% tighten
screw at this stage.




3


Step 3 : After all parts are in right
position, then 100% tighten up all
screws before using.



4




A



x4

B




x4

C



x4

D



x1

357-000004