
















069-000069

Assembly Drawing




Parts list

TOOLS






No:	Specification (W*D*H)	QTY
①	1400*750*25	1
②	800*300*16	1
③	450*60*25	1
④	750*400*16	1
⑤	750*400*16	1
⑥	603*730*16	2
⑦	603*364*16	1
⑧	396*437*16	1
⑨	396*160*16	1
⑩	390*100*16	2
⑪	306*85*16	1
⑫	317*395*4	1



Step:1








Step:2







Step:3







Step:4




Step:5




Step:6





Step:7



Step:8



Step:9



Finish

