Material List





(B part)







1 Piece left leg

1 Piece right leg

2 pcs decking strats

2 pcs decking strats (with a whole in the middle)

1 piece fabric basket

8 pcs



installation screws

1 piece table top

THE ORDER OF INSTALLATION



1

Place the Decking struts (A pieces) in the fabric basket and mount them to

Screw the upper connection (B parts) struts to the skeleton.











Mount the chipboard to the skeleton from the hole points in the profile.