



Step 1

Assembly diagram for Step 1. Part 1 is attached to part 3 using screws C. Part 2 is attached to part 3 using screws C. Part 4 is attached to part 3 using screws C.

C	x6
---	----

Step 2

Assembly diagram for Step 2. Part 5 is attached to part 3 using screws C. Part 6 is attached to part 3 using screws A+B.

A	x2
B	x2
C	x2

Step 3

Assembly diagram for Step 3. Part 7 is attached to part 3 using screws A+B. Part 8 is attached to part 3 using screws A+B.

A	x4
B	x4

Step 4

Assembly diagram for Step 4. Part 1 is attached to part 3 using screws A+B. Part 2 is attached to part 3 using screws A+B.

A	x2
B	x2

Step 5

Assembly diagram for Step 5. Part 4 is attached to part 3 using screws C. Part 5 is attached to part 3 using screws C. Part 6 is attached to part 3 using screws D.

C	x2
D	x4

Step 6

Assembly diagram for Step 6. Part 7 is attached to part 3 using screws A+B. Part 8 is attached to part 3 using screws A+B.

A	x4
B	x4

Complete

Final assembly diagram showing the completed two-tiered table.