















1  x2	2  x2	3  x1	4  x1	5  x1
6  x1	7  x1	8  x1	9  x1	10  x1
11  x1	12  x1	13  x1	14  x5	15  x1
16  x1	A  x50	B  x50	C (6.3x50mm)  x16	D (3.5x12mm)  x32
E  x4	F  x1	G  x1		

Step 1




A

x8

B

x8

Step 2




A

x6


B

x6


Step 3




Step 4




Step 5




Step 6




Step 7



Step 8




Step 9



A x6


B x6

Step 10



C x2


Step 11



D x24

E x4

Step 12



D x8

F x1

G x1

Complete

