













230-000144


1  X1	2  X1	3  X1	4  X1
5  X1	6  X1	7  X1	8  X1
9  X1	10  X1	11  X1	12  X1
13  X1	A  X32	B  X32	C (6.3X50)  X6
E  X3	F  X1	G  X1	D (3.5X12)  X23
	H  X3	I  X1	

Step 1




A	x4
B	x4

Step 2




A	x4
B	x4

Step 3




A	x6
B	x6

Step 4




A	x2
C	x4
B	x2

Step 5




A	x2
B	x2

Step 6




A	x6
B	x6

Step 7




C	x2
---	----

Step 8




A	x4	D	x1
B	x4	G	x1

Step 9




A	x4	D	x1
B	x4	G	x1

Step 10



D	x22
E	x3
F	x1

Step 11



H	x3
I	x1

Complete

