

ASSEMBLY INSTRUCTION

381-000014

PLEASE FOLLOW INSTRUCTION LISTED BELOW IN THE PROPER SEQUENCE AS NUMBERED TO ASSURE FAST, EASY AND CORRECT ASSEMBLY.


HARDWARE LIST

NO	DESCRIPTION	QTY
A	M6 x 35mm JCBC SCREW 	4 PCS
B	FLAT WASHER 	6 PCS
C	HEX NUT 	6 PCS
D	CSK SCREW M4 x 30mm 	20 PCS
E	SPANNER 	1 PC
F	M4 ALLEN KEY 	1 PC


PART LIST

NO	DESCRIPTION	QTY
1	TABLE TOP	1 PC
2	LEG	4 PCS
3	CONNECTOR	1 PC
4	OCTAGON	2 PCS
5	LEG SUPPORT	2 PCS
6	SUPPORT	2 PCS


STEP 1




STEP 2



STEP 3



STEP 4



FULLY SETUP